

## Drives and Traction & Electromagnetic Compatibility

### ASSIGNMENT 1

## Section A

Answer **ALL** questions in this section.

- A1. a) The armature of a 6-pole DC generator has 30 slots and in each slot there are 8 conductors. The flux per pole is 0.0174Wb. When the speed of the armature is 1200 rev/min. Calculate the value of the EMF generated if the armature is:
- i) Wave wound, and (3 marks)
  - ii) Lap wound. (3 marks)
- b) Motor is machine converse electrical energy to mechanical energy (2 marks)  
as shown in Figure A1b, describe basic construction of a DC motor.




Figure A1b

- A2. When an induction motor is connected to a 3-phase supply, current flows in the primary circuit. There are four kinds of power losses. With the aim of Fig. A2, describe the meanings of:
- a) Stator copper loss,  $P_{cu1}$ ; (2 marks)
  - b) Iron loss,  $P_i$ ; (2 marks)
  - c) Rotor copper loss,  $P_{cu2}$ ; (2 marks)
  - d) Mechanical loss;  $P_{loss}$ . (2 marks)




Fig.A2

- A3. a) A 4-pole, 50 Hz, 3-phase induction motor is running at a slip of 3 % on the full-load condition, determine:
- i) the synchronous speed; (2 marks)
  - ii) the motor speed; (2 marks)
- b) Describe two approaches to reduce the Electromagnetic Interference (EMI) effect. (4 marks)
- 
- A4. a) Draw the connection circuit diagrams of the following self-excited d.c. motors.
- i) The shunt motor; (2 marks)
  - ii) The compound motor. (2 marks)
- b) Regarding traction motors to drive a train, describe two kind of resistive forces for a train needed to overcome. (4 marks)

A5. A 400V DC shunt motor shown in Figure A5, it runs at no load at 1500 rpm with input 1000W. The shunt field current is 1A and the armature resistance is  $0.2\Omega$ . Find:

- i) Line current at no load, (1 mark)
- ii) Armature current at no load, (1 mark)
- iii) Armature copper loss at no load, (2 marks)
- iv) Line current at which maximum efficiency occurs, and (2 marks)
- v) The value of maximum efficiency (2 marks)




Figure A5

## Section B

Choose ALL questions from this section. Each question carries equal marks.

- B1. (a) Suggest method to maximize the starting torque of induction motor. (6 marks)

A typical torque versus slip of a cage type induction motor is shown in Fig. B1a.




Fig.B1a

- (b) Fig. B1b shows a direct on line motor start control circuit. The circuit has 3-phase power wire connected with a motor and a control circuit.

- (i) How the contactor circuit start the motor; (5marks)  
(ii) List the function of the circuit. (5marks)




Fig. B1b

- (c) Explain why Permanent Magnet Synchronous Motor (PMSM) save more energy compare to induction motor. (4 marks)

B2 (a) Describe the operation principle of below electronic component use in motor drive:

(i) Diode, (3marks)

(ii) IGBT. (3marks)

(b) There are 5 parts in EN50121, which is Electromagnetic compatibility standard. Describe each part regarding EN50121.

i) Part 1 General introduction, (2marks)

ii) Part 2 Interface between the railway system and the outside world, (3marks)

iii) Part 3 The train and complete vehicle, train-borne apparatus, (3marks)

iv) Part 4 signaling and telecommunication (3marks)

v) Part 5 Power supply (3marks)

B3. (a) Explain the necessity for using a starter with a d.c. motor. (6 marks)

(b) During regenerative braking, motor become a generator. A d.c. shunt generator as shown in Fig. B4 has the following characteristics: (6 marks)

- 125 kW rated power
- 375 V rated voltage
- 1210 rpm rated speed
- power loss of the armature circuit at full load is 8 kW
- power loss of the field circuit at full load is 2 kW

At full load, calculate:

- i. The output current,  $I_t$ ; (2 marks)
- ii. The field circuit current,  $I_f$ ; (2 marks)
- iii. The armature current,  $I_a$ ; (2 marks)
- iv. The resistance of armature circuit,  $R_a$ ; (2 marks)
- v. The resistance of field circuit,  $R_f$ ; (3 marks)
- vi. The driven torque. (3 marks)




Fig. B3

- End of Questions -

**Useful Formulae:**

The symbols used in the following formulas correspond to their usual meanings.

**DC Machines:**

Parallel path (c)	Lap winding = $2p$ ; Wave winding = 2	Induced voltage	$E = \frac{Z}{c} \times (\frac{2pN\phi}{60})$ $E = K\phi N$
Motor armature voltage	$V = E + I_a R_a$	Generator armature voltage	$V = E - I_a R_a$
Motor torque	$P = EI_a = T\omega = T(\frac{2\pi N}{60})$ $T = K\phi I_a$	Power on no load test ( $P_{NO}$ )	$P_{NO} = P_W + I_f^2 R_f + I_a^2 R_a$
Total loss	$P_L = P_o + I_f^2 R_f + I_a^2 R_a$ Where at no load test: $P_o = VI_o$	Starting resistance,	$R_s = \frac{V}{I_s} - R_a$
Shunt motor: Efficiency,	$\eta = \frac{P_{in} - P_L}{P_{in}} = \frac{V(I_a + I_f) - P_L}{V(I_a + I_f)}$	Shunt generator: Efficiency	$\frac{P_{out}}{P_{out} + P_L} = \frac{V(I_a - I_f)}{V(I_a - I_f) + P_L}$

**Induction Motors:**

Rotor Frequency	$f_r = sf$	Synchronous Speed $N_s$	$N_s = 60 f/p$
Rotor reactance per phase	$X_r = 2\pi f_r L = 2\pi s f L$ $= sX_o$	Slip	$s = \frac{N_s - N_R}{N_s} \times (100\%)$
Starting current	$I_o = \frac{E_o}{Z_o} = \frac{E_o}{\sqrt{R^2 + X_o^2}}$	Rotor impedance per phase	$Z_R = \sqrt{R^2 + (sX_o)^2}$
Ratio of power	$P_{AG} : P_{CU2} : P_M =$ $1 : s : (1-s)$	Running current	$I_R = \frac{E_R}{Z_R} = \frac{sE_o}{\sqrt{R^2 + (sX_o)^2}}$
Torque- Slip	$T = \frac{3E_2}{2\pi n_s} \times \frac{sR_2}{R_2^2 + s^2 X_2^2}$	Max. Torque Slip Equation	$s_m = \frac{R_2}{X_2}$
Efficiency	$\eta = \frac{P_{out}}{P_{out} + P_L}$		

**Synchronous Machine:**

Voltage regulation	$E = \sqrt{[V\cos\phi + IR]^2 + (V\sin\phi \pm IX_s)^2}$ $VR = \frac{E - V}{V} \times 100\%$	
--------------------	---	--

\*\*\* End \*\*\*